## B - (Black) - Power/Ground

| | |
|---|---|
| 1 = Ground | 12 = Ground |
| 2 = +12VDC | 11 = +12VDC (IN) |
| 3 = --- | 10 = --- |
| 4 = 5V OUT | 9 = 5V OUT |
| 5 = --- | 8 = --- |
| 6 = --- | 7 = --- |

## C - (Green) - Analog Sensor

| | |
|---|---|
| 1 = Port Volts | 12 = Stbd Volts |
| 2 = Port Fuel | 11 = Stbd Fuel |
| 3 = Port Eng Temp | 10 = Stbd Eng Temp |
| 4 = Port Tran PSI | 9 = Stbd Tran PSI |
| 5 = Port Oil PSI | 8 = Stbd Oil PSI |
| 6 = Port Tran Temp | 7 = Stbd Tran Temp |

## D - (Brown) - Pulse/Alarm

| | |
|---|---|
| 1 = P RPM | 12 = S RPM |
| 2 = Ground | 11 = Ground |
| 3 = Alarm Out | 10 = G RPM |
| 4 = --- | 9 = --- |
| 5 = --- | 8 = --- |
| 6 = Ground | 7 = Ground |

## A - (Grey) - Indicator/Status

| | |
|---|---|
| 1 = Status 6-H | 12 = Status 1-H |
| 2 = Status 7-H | 11 = Status 0-H |
| 3 = Status 5-H | 10 = Status 2-H |
| 4 = Status 4-H | 9 = Status 3-H |
| 5 = Status 11/Relay 3 | 8 = Status 8/Relay 0 |
| 6 = Status 10/Relay 2 | 7 = Status 9/Relay 1 |